



PORTS AND YACHTING DIRECTORATE

LOCAL NOTICE TO MARINERS No 043 OF 2021

Our Ref: **MT/PYD/0001/21**

30 April 2021



Transport Malta

Malta Transport Centre,
Triq Pantar, Hal Lija, LJA 2021
Malta

Tel: (356) 2122 2203
Fax: (356) 2125 0365
Email: info.tm@transport.gov.mt

www.transport.gov.mt

Refurbishment works on Marfa breakwater at Ir-Ramla tal-Bir in Il-Fliegu ta' Kemmuna

The Ports and Yachting Directorate, Transport Malta, notifies mariners and the general public that refurbishment work on the Marfa breakwater at Ir-Ramla tal-Bir in Il-Fliegu ta' Kemmuna (Malta side) will start on Tuesday 4th May 2021 and will continue until further notice.

A silt curtain will be laid along the imaginary line A, B, C, D and E as shown on attached chart. Lit up marker buoys will be laid at points B, C and D.

	LATITUDE (N)	LONGITUDE (E)
A	35° 59'.221	014° 20'.642
B	35° 59'.257	014° 20'.660
C	35° 59'.242	014° 20'.697
D	35° 59'.214	014° 20'.675
E	35° 59'.205	014° 20'.652


Some of the work will be carried out by scuba divers and they will be displaying the International Code of Signals flag "A".

Due to the above-mentioned works no vessel shall enter the area, therefore no vessel will be allowed to berth alongside the breakwater whilst the work is being carried out.

Mariners are to keep a sharp lookout, navigate with caution and at very slow speed when in the vicinity and are to give the indicated areas a wide berth, they are to co-operate with the contractor on site.

All mariners are to comply with any instructions given on VHF Channel 12 and/or 16, by Valletta VTS and by any Enforcement Personnel on site.

Chart affected: **BA 211**



© Transport Malta all rights reserved

DISCLAIMER

Whilst the Ports and Yachting Directorate, Transport Malta has endeavoured to ensure that the material supplied is suitable for the purpose described, it accepts no liability (to the maximum extent permitted by law) for any damage or loss of any nature arising from its use.
The material supplied is used entirely at the Recipient's own risk.