



PORTS AND YACHTING DIRECTORATE

LOCAL NOTICE TO MARINERS No 176 of 2022

Our Ref: **TM/PYD/ 0001/22**

10 October 2022



Transport Malta

Malta Transport Centre,
Triq Pantar, Hal Lija, LJA 2021
Malta

Tel: (356) 2122 2203
Fax: (356) 2125 0365
Email: info.tm@transport.gov.mt

www.transport.gov.mt

Danger due to protruding studs at Għar Lapsi slipway

The Ports and Yachting Directorate, Transport Malta, notifies mariners that there are protruding steel studs at Għar Lapsi slipway which is in the following approximate position:

Latitude (N)	Longitude (E)
35° 49'.634	14° 25'.459

Due to damaged wooden strips on the slipway at Għar Lapsi there are a number of steel studs protruding from the concrete which could damage any vessel while it is being launched or taken out of the sea. There is also a danger of injury to anybody that uses the slipway.

Due to the above mariners are advised to use the other slipway or pay special attention while it is being used, until it is repaired.

Chart Affected: **BA Chart 2538**