



PORTS AND YACHTING DIRECTORATE

## LOCAL NOTICE TO MARINERS N° 138 of 2023

Our Ref: **TM/PYD/0001/23**

25 July 2023



**Transport Malta**

Malta Transport Centre,  
Triq Pantar, Hal Lija, LJA 2021  
Malta

Tel: (356) 2122 2203  
Fax: (356) 2125 0365  
Email: [info.tm@transport.gov.mt](mailto:info.tm@transport.gov.mt)

[www.transport.gov.mt](http://www.transport.gov.mt)

### Maintenance works on slipway at Ir-Ramla tat-Torri, Mellieha

The Ports and Yachting Directorate, Transport Malta, notifies mariners that maintenance works will be carried out on the slipway at Ir-Ramla tat-Torri, Mellieha, as shown on the attached chart.

The works will start on Monday 31<sup>st</sup> July 2023 and will be completed by Friday 11<sup>th</sup> August 2023.

The work will be carried out from land but will involve the use of divers who will be displaying the International Code of Signals flag "A", while diving is in progress.

A silt curtain will be laid along the line joining the points A, B, C and D.


Position	Latitude (N)	Longitude (E)	
A	35° 59'.609	014° 21'.847	Coast
B	35° 59'.608	014° 21'.845	
C	35° 59'.603	014° 21'.850	
D	35° 59'.609	014° 21'.858	Coast

Due to the above, the slipway mentioned above will not be accessible while the works are being carried out. A safety distance of 10m from the silt curtain is to be kept, at all times.

Mariners and owners of vessels are to proceed at very low speed (no wake) when navigating close to the area and are to co-operate with the contractor on site.

All mariners are to comply with any instructions given on VHF Channel 12 and/or 16, by Valletta VTS and by any Enforcement Personnel on site.

Charts Affected: **BA 211**



© Transport Malta all rights reserved

DISCLAIMER

Whilst the Ports and Yachting Directorate, Transport Malta has endeavoured to ensure that the material supplied is suitable for the purpose described, it accepts no liability (to the maximum extent permitted by law) for any damage or loss of any nature arising from its use.

The material supplied is used entirely at the Recipient's own risk.