

PORTS AND YACHTING DIRECTORATE

LOCAL NOTICE TO MARINERS Nº 196 OF 2023

Our Ref: **TM/PYD 0001/23**

25 October 2023



Malta Transport Centre, Triq Pantar, Ħal Lija, LJA 2021 Malta

Tel: (356) 2122 2203 Fax: (356) 2125 0365 Email: info.tm@transport.gov.mt

www.transport.gov.mt

Repair work on the Bighi fortification wall in the Grand Harbour

The Ports and Yachting Directorate, Transport Malta, notifies mariners and the general public that repair work on the Bighi fortification wall in the Grand Harbour, will be carried out.

The works will be carried out between Wednesday 1st November 2023 and Thursday 31st October 2024.

A work area formed by the imaginary lines joining the points A, B, C and D and the intermediate coastline, as shown on the attached chart, will be established.

LATITUDE (N)	LONGITUDE (E)
35°53'.605	014°31'.551
35°53'.633	014°31'.524
35°53'.639	014°31'.512
35°53'.640	014°31'.503
	35°53'.605 35°53'.633 35°53'.639

A silt curtain will be laid within the above-mentioned areas depending on where work is being carried out.

Scuba divers will be assisting in the works and will be displaying the International Code of Signals flag "A".


Mariners are to note that due to these works no vessel is allowed to enter the abovementioned area and that the small quay within the area will not be accessible throughout the duration of the works.

Mariners and vessel operators are to navigate with caution and at slow speed (no wake) when in the vicinity. They are to co-operate with the contractor on site.

Mariners are to comply with instructions issued on VHF channel 12 and/or 16 by Valletta VTS.

Chart a	affected:
---------	-----------

BA 177



© Transport Malta all rights reserved

DISCLAIMER

Whilst the Ports and Yachting Directorate, Transport Malta has endeavoured to ensure that the material supplied is suitable for the purpose described, it accepts no liability (to the maximum extent permitted by law) for any damage or loss of any nature arising from its use.

The material supplied is used entirely at the Recipient's own risk.