

PORTS AND YACHTING DIRECTORATE

LOCAL NOTICE TO MARINERS Nº 073 of 2024

Our Ref: **TM/PYD 0001/24**

8 July 2024



Malta Transport Centre, Triq Pantar, Hal Lija, LJA 2021 Malta

 Tel:
 (356) 2122 2203

 Fax:
 (356) 2125 0365

 Email:
 info.tm@transport.gov.mt

www.transport.gov.mt

Clearing of debris and concrete works at Qui-Si-Sana - Sliema

The Ports and Yachting Directorate, Transport Malta notifies mariners and the general public that clearing of debris and some concrete works at Qui-Si-Sana – Sliema, will be carried out within the area formed by joining A to B and the intermediate coastline, as shown in red on the attached chart.

The works from the crane-barge will commence on Monday 15th July 2024 and are expected to be completed by Friday 2nd August 2024.

A silt curtain will be laid from points A to B as shown on the attached chart, on Tuesday 9th July 2024 due to some work will be done from the land side. A safety distance, of at least 10m from the silt curtains, shall be maintained at all times.

POSITION	LATITUDE (N)	LONGITUDE (E)
A	35°54'.506	14°30'.714
В	35°54'.496	14°30'.722

The works will be carried out with the use of a crane-barge which will be moored centred on the following position:


LATITUDE (N)	LONGITUDE (E)
35°54'.506	14°30'.732

Some of the works will be carried out by scuba divers who will be displaying the International Code of Signals flag "A".

Mariners and vessel operators are to navigate with caution and at slow speed (no wake) when in the vicinity. They are to co-operate with the contractor on site.

Mariners are to comply with instructions issued on VHF channel 12 and/or 16 by Valletta VTS.

Chart affected:



© Transport Malta all rights reserved

DISCLAIMER

Whilst the Ports and Yachting Directorate, Transport Malta has endeavoured to ensure that the material supplied is suitable for the purpose described, it accepts no liability (to the maximum extent permitted by law) for any damage or loss of any nature arising from its use.

The material supplied is used entirely at the Recipient's own risk.